

**Government of Jammu & Kashmir**  
**MECHANICAL HOSPITAL & CENTRAL HEATING DIVISION, SRINAGAR**  
**-----Tele-Fax: 0194-2496089, Email ID: xenmhchdk@yahoo.in-----**

The General Manager,  
JKMSCL.

No:-MHCHD/TS/ 226-28

Dated:-23.09/2018

**Sub:- Evaluation of sample for the finalization of rate contract for the procurement of hospital furniture.**

Ref:- G.M, J&K Medical Supply Corporation Office letter No:-JKMSCL/GM/PS/2018/3943-51 dated 22/03/2018.

Sir,

In view to above reference a technical committee comprising of team of Mechanical Engineers from Mechanical Engineering Department, Jammu/Kashmir was framed for inspection of the hospital furniture samples at warehouse of Medical Corporation and have submitted their report (attached).

In this connection you are requested to kindly convene a meeting as per suitability of all associated members for ratification of the submitted report.

Yours Faithfully,

(Er. Mubashir Nazir Naqashbandi)

Executive Engineer,

MHCHD, Srinagar.



Copy to the:-

1. Chief Engineer, Mechanical Engineering Department, Kashmir for information.
2. Superintending Engineer, Mechanical Circle, MED, Srinagar for information.

405/ps/gm/mscl/18  
14/09/18

**Comparative sheet of Physical Evaluation of hospital furniture samples stored at warehouse of J&K medical Supplies Corporation at Amphalla Jammu by team of engineers from MED Jammu/Kashmir**

| S. No. | Co de   | Name of item                 | Sample codes   |                             |       |  |  |  |  |  |       | Remarks  |
|--------|---------|------------------------------|--|-----------------------------|-------|--|--|--|--|--|-------|--|
|        |         |                              | 111 A  | 222 A                       | 333 A | 444 A  | 555 A  | 666 A  | 777 A  | 888 A  | 999 A |  |
| 1.     | HFS-001 | ICU BED/CCU BED/RECOVERY BED | Approved   | Sample Not Provided (S.N.P) | S.N.P | Approved   | S.N.P  | Approved Subject to condition that bottle holder is provided.  | S.N.P  | Rejected<br>1.mattress not in single section<br>2.laminated board not used in back rest section.<br>3.traction pulley not attached.  | S.N.P | Mattress density and material cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended.<br>Units of density are not mentioned in the specifications of the tender. Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 2.     | HFS-002 | FOWLER BED                   | Approved Subject to condition that 1.Crib and attachments are provided. 2.overall height 600mm is with castor without mattress and not without castor, without mattress as specified in technical specificatio | S.N.P                       | S.N.P | Approved Subject to condition that 1.Crib and attachments are provided. 2.overall height 600mm is with castor without mattress and not without castor, without mattress as specified in technical specifications. If it is a typing error. | Rejected 1.polymer moulded head and foot panel not provided. | Approved Subject to condition that 1.Crib and attachments are provided. 2.overall height 600mm is with castor without mattress and not without castor, without mattress as specified | Approved Subject to condition that 1.Crib and attachments are provided. 2.overall height 600mm is with castor without mattress and not without castor, without mattress as specified | Rejected 1.Crib and attachments not provided. 2.polymer moulded head and foot panels not provided. 3. slot size not as per specifications . 4. H section legs not provided. 5.PU foam 3" instead of 4" as specified in tender. | S.N.P | Mattress density and material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended.<br>Units of density are not mentioned in the specifications of the tender  |

*Handwritten signatures and initials:*  
  


|    |         |                    | ns. If it is a typing error.   |  |       |  |  | in technical specifications. If it is a typing error.  | in technical specifications. If it is a typing error. |  |   |   |
|----|---------|--------------------|--|--|-------|--|--|--|---|--|---|---|
| 3. | HFS-003 | SEMI FOWLER BED    | Approved   | S.N.P  | S.N.P | Approved<br>Subject to condition<br>1.PU foam used will be 4" specified in tender and not 3" as provided in sample | Rejected<br>1.Polymer moulded head and foot panels not provided.<br>2. saline rod not provided.<br>3.PU foam of poor quality | Approved   | Approved  | Rejected<br>1.Polymer moulded head and foot panels not provided.<br>2. H section not used.<br>3. four nos. saline rod points not provided. | Rejected<br>1.castor not provided.<br>2. perforated hole dia. is 15mm instead of 21mm as specified in tender.         | Mattress density and material cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended.<br>Units of density are not mentioned in the specifications of the tender material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 4. | HFS-004 | PLAIN HOSPITAL BED | Rejected<br>1.Not as per tendered specifications.<br>2. not reinforced as per specification. | Rejected<br>1.Not as per tendered specifications.<br>2. not reinforced as per specification. | S.N.P | Rejected<br>1.Not as per tendered specifications.<br>2. Crib not provided.   | Rejected<br>1.Not as per tendered specifications.<br>2. not reinforced as per specification.                                 | Rejected<br>1.Not as per tendered specifications.<br>2. not reinforced as per specification. | S.N.P   | Rejected<br>1.Not as per tendered specifications.<br>2. not reinforced as per specification.   | Rejected<br>1.Not as per tendered specifications.<br>2. not reinforced as per specification.<br>3. Crib not provided. | Mattress density and material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended.<br>Units of density are not mentioned in the specifications of the tender   |
| 5. | HFS-005 | PAEDIATRIC BED     | Rejected<br>1.Mattress not of specified thickness.<br>2. Poor paint quality                  | Rejected<br>1.Reinforcements not as per tendered specifications                              | S.N.P | Approved   | S.N.P  | S.N.P  | S.N.P   | S.N.P  | S.N.P   | Mattress density and material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended.<br>Units of density are not mentioned in the specifications of the tender   |
| 6. | HFS-008 | INSTRUMENT TROLLEY | Approved<br>Subject to condition   | Rejected<br>1.Not as per tendered  | S.N.P | Approved<br>Subject to condition that  | Rejected<br>1.Distance between   | Rejected<br>1.Distance   | Rejected<br>1.Distance between                        | Rejected<br>1.Distance between   | Approved<br>Subject to condition that   | Overall height asked for is 900mm and height of lower shelf demanded s  |

*Handwritten signature/initials*

|    |         |                  |   |  |       |  |  |   |  |  |   |   |
|----|---------|------------------|---|--|-------|--|--|---|--|--|---|---|
|    |         |                  | that<br>1.Distance of top shelf is 810mm from ground level and not lower shelf as specified in tender. If it is a typing error.   | specificatio<br>ns<br>2.poor finish with burrs<br>3. castor size 120mm instead of 125mm as specified in the tender.<br>4. no supports for shelves            |       | 1.Distance of top shelf is 810mm from ground level and not lower shelf as specified in tender. If it is a typing error.                                      | shelves is 490mm instead of 810mm as specified in tender.<br>2. castor size 100mm instead of 125mm as specified in the tender.<br>3. no supports for shelves | is .of as in<br>between shelves is 490mm instead of 810mm as specified in tender.<br>2. poor finish.<br>3. no supports for shelves  | shelves is 490mm instead of 810mm as specified in tender.<br>2. poor finish.<br>3. sharp corners.  | shelves is 650mm instead of 810mm as specified in tender.<br>2. castor size 100mm instead of 125mm as specified in the tender.<br>3.railings are not provided.               | 1.Distance of top shelf is 810mm from ground level and not lower shelf as specified in tender. If it is a typing error. | 330mm from ground level and height of second shelf demanded is 810 mm from lower shelf. This sums upto 1140mm which is above 900mm.. correction in specification of height is needed.<br>Also material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended.  |
| 7. | HFS-009 | CRASH CART       | Rejected<br>1.Not as per specification.<br>2. poor finish   | Rejected<br>1.Not as per specification.<br>2. poor quality<br>3. boxes inside drawer not provided  | S.N.P | Approved   | Approved<br>Subject to condition that 1.boxes inside drawer are provided, which are missing in sample  | Approved  | Approved<br>Subject to condition that 1.Laminat e size as per tendered specification is provided   | Approved<br>Subject to condition that 1.boxes inside drawer are provided, which are missing in sample  | S.N.P   | Material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended.  |
| 8. | HFS-010 | DRESSING TROLLEY | Approved<br>Subject to condition that 1.Distance of top shelf is 810mm from ground level and not lower shelf as specified in tender. If it is a typing error 2. bucket lid is provided which is missing in sample | Approved<br>Subject to condition that 1.Distance of top shelf is 810mm from ground level and not lower shelf as specified in tender. If it is a typing error | S.N.P | Approved<br>Subject to condition that 1.Distance of top shelf is 810mm from ground level and not lower shelf as specified in tender. If it is a typing error | S.N.P  | Approved<br>Subject to condition that 1.Distance of top shelf is 810mm from ground level and not lower shelf as specified in tender. If it is a typing error 2. bucket as per specified height and with | Rejected<br>1.Distance between shelves is 480mm and not 810mm as per tendered specification<br>2.bucket not as per specification<br>3. proper supports not provided as tendered. | Rejected<br>1.Distance between shelves is 480mm and not 810mm as per tendered specification<br>2.bucket without lid.<br>3. removable stays for bucket and bowl not provided. | S.N.P   | Overall height asked for is 900mm and height of lower shelf demanded is 330mm from ground level and height of second shelf demanded is 810 mm from lower shelf. This sums upto 1140mm which is above 920mm. correction in specification of height is needed.<br>Also material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended. |

Handwritten signatures and initials at the bottom left corner of the page.

|     |         |                                |  |  |       |  |  |  |  |   |       |  |
|-----|---------|--------------------------------|--|--|-------|--|--|--|--|---|-------|--|
| 9.  | HFS-011 | STRETCHER TROLLEY.             | Approved   | Approved   | S.N.P | Approved<br>Subject to condition that 1.IV rod is provided which is missing in sample. | Rejected<br>1.not as per tendered specification<br>2.castor size 125mm instead of 200mm as per tendered specification                  | Rejected<br>1.Material used is not aluminium as per tendered specification | Approved   | Rejected<br>1.castor size 150mm instead of 200mm as per tendered specification<br>2.IV rod not provided | S.N.P | material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended. |
| 10. | HFS-012 | EMERGENCY AND RECOVERY TROLLEY | Approved   | S.N.P  | S.N.P | Approved   | Rejected<br>1.Xray cassette holder,safety belts and saline rod not provided.<br>2.PU foam attached with bed.                           | Approved   | Approved   | Rejected<br>1.M.S. tray, cylinder holder and safety belts not provided                                  | S.N.P | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended.  |
| 11. | HFS-013 | EXAMINATION COUCH              | Rejected<br>1.lower middle section not as per tendered specification | S.N.P  | S.N.P | Rejected<br>1.lower middle section not as per tendered specification                   | Rejected<br>1.lower middle section not as per tendered specification<br>2.BP tray not provided<br>3.poor paint quality and poor finish | Rejected<br>1.lower middle section not as per tendered specification       | Rejected<br>1.lower middle section not as per tendered specification | Rejected<br>1.lower middle section not as per tendered specification                                    | S.N.P | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended.  |
| 12. | HFS-014 | SOLID LINEN TROLLEY            | Approved   | Rejected<br>1.linens quality poor<br>2.poor finish with burr | S.N.P | Approved   | Rejected<br>1.overall size 920mmx510mm instead of 960mmx510mm as tendered.<br>2.castor size 100mm instead                              | Rejected<br>1.poor quality canvas<br>2.frame unstable                      | Approved   | Rejected<br>1.overall size 930mmx510mm instead of 960mmx510mm as tendered.<br>2.castor size 110mm       | S.N.P | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended.  |

AS  
WJE

|     |         |                                 |  |   |   |   |   |   |   |   |   |   |
|-----|---------|---------------------------------|--|---|---|---|---|---|---|---|---|---|
|     |         |                                 |  |   |   |   | of125mm                                     |   |   | instead of125mm                             |   |   |
| 13. | HFS-015 | WASH BASIN STAND TWO TIER       | Approved   | Rejected Not as per tendered specifications | S.N.P   | Rejected Not as per tendered specifications | Approved                                    | S.N.P   | Approved  | Approved                                    | Approved                                    | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 14. | HFS-016 | KICK BUCKET                     | Approved   | Rejected Not as per tendered specifications | S.N.P   | Approved                                    | Rejected Not as per tendered specifications | S.N.P   | Approved  | Rejected Not as per tendered specifications | Rejected Not as per tendered specifications | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 15. | HFS-017 | SALINE STAND WITH SS ROD        | Approved   | Rejected Not as per tendered specifications | Rejected Not as per tendered specifications Height less | Approved                                    | Rejected Not as per tendered specifications | Approved  | Rejected Not as per tendered specifications Round knob used instead of star knob. | Rejected Not as per tendered specifications | Approved                                    | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 16. | HFS-018 | REVOLVING STOOL                 | Rejected Not as per tendered specifications revolving top 290mm instead of 305mm | Approved                                    | Approved  | Approved                                    | Approved                                    | Rejected Not as per tendered specifications revolving top less than 305mm | Approved  | Approved                                    | Rejected Unstable at 755mm height           | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 17. | HFS-019 | BED SIDE TOOL/ALL PURPOSE STOOL | Rejected Round pipes used instead of c channels                                  | S.N.P                                       | S.N.P   | Approved                                    | S.N.P                                       | Rejected Rectangular channel used instead of c channels                   | Approved  | Rejected Not as per specifications          | S.N.P                                       | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 18. | HFS-020 | DOUBLE STEP STOOL               | Rejected Not as per tendered specifications                                      | Rejected Not as per tendered specifications | S.N.P   | Rejected Not as per tendered specifications | Rejected Not as per tendered specifications | Rejected Not as per tendered specifications                               | Rejected Not as per tendered specifications                                       | Rejected Not as per tendered specifications | Approved                                    | material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |

*Handwritten signatures and initials:*  
 A.S. [Signature]  
 W.S. [Signature]

|     |         |                              |   |  |  |  |       |   |          |  |   |       |   |
|-----|---------|------------------------------|---|--|--|--|-------|---|----------|--|---|-------|---|
| 19. | HFS-021 | BIRTHING BED (non motorised) | Rejected<br>Not as per specifications, foot bow not provided, PU foam size less than 75mm | S.N.P  | S.N.P  | Approved   | S.N.P | S.N.P   | S.N.P    | S.N.P  | S.N.P   | S.N.P | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 20. | HFS-022 | WHEEL CHAIR                  | Approved  | S.N.P  | Rejected<br>Not as per tendered specifications | Rejected<br>Not as per tendered specifications                   | S.N.P | S.N.P   | Approved | Approved   | S.N.P   | S.N.P | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 21. | HFS-024 | CYLINDER TROLLEY             | Rejected<br>Not as per tendered specifications  | Rejected<br>Not as per tendered specifications, castor of poor quality | Rejected<br>Not as per tendered specifications | Rejected<br>Not as per tendered specifications base not of steel | S.N.P | Rejected<br>Not as per tendered specifications base steel of poor quality | Approved | Rejected<br>Not as per tendered specifications base not of steel | Rejected<br>Not as per tendered specifications, base not of steel, castor of poor quality | S.N.P | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 22. | HFS-025 | CRITICAL PATIENTS TROLLEYS   | S.N.P   | S.N.P  | S.N.P  | S.N.P  | S.N.P | Rejected<br>Not as per tendered specifications, poor finish               | S.N.P    | S.N.P  | S.N.P   | S.N.P | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 23. | HFS-026 | HOSPITAL LOCKER PIGEON HOLE  | S.N.P   | S.N.P  | S.N.P  | S.N.P  | S.N.P | Approved  | Approved | S.N.P  | S.N.P   | S.N.P | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 24. | HFS-027 | STEEL ALMIRAH BIG            | S.N.P   | S.N.P  | S.N.P  | S.N.P  | S.N.P | Approved  | Approved | S.N.P  | S.N.P   | S.N.P | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |
| 25. | HFS-028 | STEEL ALMIRAH SMALL          | S.N.P   | S.N.P  | S.N.P  | S.N.P  | S.N.P | Approved  | Approved | Approved   | S.N.P   | S.N.P | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended. |

9/10

Handwritten initials and marks at the bottom left corner of the page.

|     |         |   |   |   |  |          |   |   |   |   |   |  |
|-----|---------|---|---|---|--|----------|---|---|---|---|---|--|
| 26. | HFS-029 | COMPUTER CHAIR REVOLVING                | S.N.P                                       | S.N.P   | S.N.P  | S.N.P    | S.N.P                                   | Approved  | Approved                                    | Approved                                    | S.N.P   |  |
| 27. | HFS-030 | STRECHTER FOLDING                       | Approved                                    | S.N.P   | Approved                                     | S.N.P    | S.N.P                                   | Rejected Canvas quality poor                                  | Approved                                    | S.N.P                                       | Approved  |  |
| 28. | HFS-031 | OVER BED TABLE                          | Rejected Welding not used                   | Rejected Not as per tendered specifications, Under size | Rejected Not as per tendered specifications, | Approved | Approved                                | Approved  | Approved                                    | Approved                                    | Rejected Not as per tendered specifications, rectangular bars used instead of tube is used. | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended |
| 29. | HFS-032 | PERFORATED STEEL BENCH                  | S.N.P                                       | S.N.P   | S.N.P  | S.N.P    | S.N.P                                   | Rejected Poor paint finish, chrome plated handle not provided | Rejected Chrome plated handle not provided  | S.N.P                                       | S.N.P   | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended |
| 30. | HFS-033 | THREE SEATER BENCH SUPERIOR QUALITY     | S.N.P                                       | S.N.P   | S.N.P  | S.N.P    | Rejected Perforated seats base not used | Approved  | Approved                                    | S.N.P                                       | S.N.P   | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended |
| 31. | HFS-034 | SURGEON'S STOOL WITH BACK REST          | Rejected Not as per specifications          | S.N.P   | S.N.P  | S.N.P    | S.N.P                                   | S.N.P   | S.N.P                                       | Rejected Poor quality rusted                | S.N.P   |  |
| 32. | HFS-035 | GYNAE EXAMINATION TABLE(PLAIN)          | Approved                                    | Approved  | S.N.P  | Approved | Approved                                | Approved  | Approved                                    | Rejected Not as per tendered specifications | S.N.P   | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended |
| 33. | HFS-036 | SCOOP STRETCHER                         | Rejected Not as per tendered specifications | S.N.P   | Rejected Not as per tendered specifications  | S.N.P    | S.N.P                                   | S.N.P   | Rejected Not as per tendered specifications | Rejected Not as per tendered specifications | S.N.P   |  |
| 34  | HFS-037 | SPINE BOARD WITH STRAPS AND HEAD BLOCKS | Approved                                    | S.N.P   | Approved                                     | S.N.P    | S.N.P                                   | S.N.P   | Approved                                    | Approved                                    | S.N.P   |  |

Handwritten initials and marks at the bottom left corner of the page.



|                                   |         |                     |          |       |   |       |       |       |          |       |                             |  |
|-----------------------------------|---------|---------------------|----------|-------|---|-------|-------|-------|----------|-------|-----------------------------|--|
| 35.                               | HFS-038 | WHEEL CHAIR FOLDING | S.N.P    | S.N.P | Rejected Not as per tendered specifications | S.N.P | S.N.P | S.N.P | S.N.P    | S.N.P | S.N.P                       | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended |
| 36.                               | HFS-039 | BACK REST           | S.N.P    | S.N.P | S.N.P                                       | S.N.P | S.N.P | S.N.P | S.N.P    | S.N.P | S.N.P                       |  |
| 37.                               | HFS-040 | INSTRUMENT CABINET  | Approved | S.N.P | S.N.P                                       | S.N.P | S.N.P | S.N.P | Approved | S.N.P | S.N.P                       | Material quality and grade cannot be checked visually or by hand therefore test certificates and third party inspection is recommended |
| Total no of samples for each code |         |                     | 28       | 15    | 9   | 23    | 17    | 26    | 29       | 26    | 11                          |  |
|                                   |         |                     |          |       |   |       |       |       |          |       | Total no of samples checked | 184  |

**General Note:-**

The nature of the material needs to be corroborated in case of stainless steel where ever mentioned in technical specifications by providing metallurgical test certificates. The epoxy paint thickness and quality cannot be visualized from samples and the successful bidder may be asked to provide test certificates from any reputed lab. Mattress density and material quality and grade cannot be checked visually or by hand, therefore test certificates and third party inspection is recommended. During the evaluation of samples **No Test Certificate** of any sample were provided. Moreover all the samples during inspection were in assembled conditions and were coded by the authorities of the Medical Corporation.

At many places as reflected in above comparative statement subjective approval of samples is recommended. Although this committee is not mandated for such, however since there are minor lacunae's in samples which the committee feels can be corrected without any structural changes, recommendations for their subjective inclusions has been made. This will also ensure competitiveness of rates.

**Report:-**


The above physical comparative statement has been framed against the requisition letter from General Manager, JKMSCL vide no. JKMSCL/GM/PS/2018/3943-51, Dated: 22-03-2018 and subsequent orders issued by Executive Engineer, MHCHD, Srinagar vide no. MHCHD/Estt/11-17, Dated:- 4-4-2018 & Executive Engineer, MHCHD Jammu office order no. 01 of 2018 Dated: 05-04-2018 endorsed vide no. MHDJ/Tech/89-96 Dated;- 05-04-2018.

- 1) HFS-001, ICU Bed/CCU Bed/Recovery Bed 111A, 444A are approved and 666A is approved if it provides the ICD bottle holder which is missing in the sample .
- 2) HFS-002, Fowler Bed 111A and 444A are approved only if cribs and attachments are provided which are missing in samples. Moreover 111A, 444A,666A and 777A are approved on the condition that overall height 600mm is with castor, without mattress and 600mm without mattress, without castor is a typing error.
- 3) HFS-003,Semi Fowler Bed,111A,666A and 777A are approved and 444A is approved on the condition that 4" PU foam mattress is provided and not 3" as given in sample.

- 4) HFS-004, Plain Hospital Bed, no item is approved as none corresponds to the technical specifications of the tender.
- 5) HFS-005, Paediatric Bed, only 444A is approved.
- 6) HFS-008, Instrument Trolley, 111A, 444A and 999A are approved only if distance of top shelf is 810mm from ground and not between shelves. If there is a typing error in technical specifications.
- 7) HFS-009, Crash Cart, 444A and 666A are approved and 555a and 888A are approved if boxes inside drawer are provided and 777A is approved laminate board of tendered specification is provided.
- 8) HFS-010, Dressing trolley 111A, 222A, 444A and 666A are approved only if height of top shelf is 810mm from ground level and not from bottom shelf as specified in tender. If it is a typing error in tendered specifications. Also 111A has to provide bucket lid and 666A has to provide bucket of proper tendered specifications with lid.
- 9) HFS-011, Stretcher Trolley, 111A, 222A and 777A are approved and 444A is approved if IV rod is provided which is missing in sample.
- 10) HFS-012, Emergency and Recovery Trolley, 111A, 444A, 666A and 777A are approved.
- 11) HFS-013, Examination Couch, no sample is approved as none corresponds to tendered specifications.
- 12) HFS-014, Solid Linen Trolley, 111A, 444A and 777A are approved.
- 13) HFS-015, Wash Basin Stand Two Tier, 111A, 555A, 777A, 888A and 999A are approved.
- 14) HFS-016, Kick Bucket, 111A, 444A and 777A are approved.
- 15) HFS-017, Saline Stand with SS rod, 111A, 444A, 666A and 999A are approved.
- 16) HFS-018, Revolving Stool, 222A, 333A, 444A, 555A, 777A and 888A are approved.
- 17) HFS-019, Bed Side Stool/All purpose Stool, 444A and 777A are approved.
- 18) HFS-020, Double Step Stool, only 999A is approved.
- 19) HFS-021, Birthing Bed (non motorised) only 444A is approved.
- 20) HFS-022, Wheel chair, 111A, 777A and 888A are approved.
- 21) HFS-024, Cylinder Trolley, only 777A is approved.
- 22) HFS-025, Critical Patients Trolley, only one sample was given and it is not approved.
- 23) HFS-026, Hospital Locker Pigeon Hole, 666A and 777A are approved.
- 24) HFS-027, Steel Almirah Big, 666A and 777A are approved.
- 25) HFS-028, Steel Almirah Small, 666A, 777A and 888A are approved.
- 26) HFS-029, Computer Chair Revolving, 666A, 777A and 888A are approved.
- 27) HFS-030, Stretcher Folding, 111A, 333A, 777A and 999A are approved.
- 28) HFS-031, Over Bed Table, 444A, 555A, 666A, 777A and 888A are approved.
- 29) HFS-032, Perforated Steel Bench, no sample is approved.
- 30) HFS-033, Three Seater Bench Superior Quality, 666A and 777A are approved.
- 31) HFS-034, Surgeon Stool with Back Rest, no sample is approved.
- 32) HFS-035, Gynae examination Table (Plain), 111A, 222A, 444A, 555A, 666A and 777A are approved.
- 33) HFS-036, Scoop Stretcher, no sample is approved.


*Handwritten initials and marks:*  
A  
ME  
W/S  
JS

- 34) HFS-037, Spine Board with Straps and Head Blocks, 111A,333A,777A and 888A are approved.
- 35) HFS-038, Wheel Chair Folding. no sample is approved.
- 36) HFS-039. Back Rest. no sample is given.
- 37) HFS-040. Instrument cabinet. 111A and 777A are approved.




18.04.18

Er. Reyaz Ahmad Mir  
J.E MHCH, Division Srinagar



18.04.18

Er. Mudasir Sidiq Khan  
A.E MHCH, Division Srinagar



Er. Harjeet Singh  
J.E MHCH, Division Jammu



Er. Vikas Pandotra  
A.E MHCH Division, Jammu



Er. Mubashir Nazir Nagashbandi  
Executive Engineer, MH&CH Division,  
Srinagar



Er. M.S. Khorana  
Executive Engineer, MH&CH Division,  
Srinagar